# Energy performance certificate (EPC)



# **Property type**

A3/A4/A5 Restaurant and Cafes/Drinking Establishments and Hot Food takeaways

# Total floor area

441 square metres

#### Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.


If a property has an energy rating of F or G, the landlord cannot grant a tenancy to new or existing tenants, unless an exemption has been registered.

From 1 April 2023, landlords will not be allowed to continue letting a non-domestic property on an existing lease if that property has an energy rating of F or G.

You can read <u>guidance for landlords on the regulations and exemptions</u> (<u>https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment\_data/file/824018/Non-</u> Dom Private Rented Property Minimum Standard - Landlord Guidance.pdf).

#### Energy efficiency rating for this property

This property's current energy rating is C.



Properties are given a rating from A+ (most efficient) to G (least efficient).

Properties are also given a score. The larger the number, the more carbon dioxide (CO2) your property is likely to emit.

#### How this property compares to others

Properties similar to this one could have ratings:

# If newly built

# If typical of the existing stock

Breakdown of this property's energy performance

Main heating fuel Natural Gas

# **Building environment**

Heating and Natural Ventilation





35 | B

# Assessment level

3

# Building emission rate (kgCO2/m2 per year)

175.82

Primary energy use (kWh/m2 per year)

1024.35

What is primary energy use?

#### **Recommendation report**

Guidance on improving the energy performance of this property can be found in the recommendation report (/energy-certificate/4103-2829-0685-8291-0593).

#### Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

# Assessor contact details

Assessor's name **Doug Whiffen** 

## Telephone

02476 233144

#### Email

doug.whiffen@wensleylawz.com

# Accreditation scheme contact details

#### Accreditation scheme

Elmhurst Energy Systems Ltd

# Assessor ID

EES/007512 https://find-energy-certificate.digital.communities.gov.uk/energy-certificate/4389-3917-9540-7550-2469

# **Telephone** 01455 883 250

Email

enquiries@elmhurstenergy.co.uk

# **Assessment details**

Date of assessment 6 November 2020

#### Date of certificate

15 December 2020

# Employer

Wensley & Lawz Ltd

# **Employer address**

116 Walsgrave Road Coventry CV2 4ED

## Assessor's declaration

The assessor is not related to the owner of the property.

#### Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <u>mhclg.digital-</u> <u>services@communities.gov.uk</u>, or call our helpdesk on 020 3829 0748.

There are no related certificates for this property.

# Energy performance certificate (EPC) recommendation report

THE UNICORN HOTEL WEST STREET SOMERTON TA11 7PR Certificate number 4103-2829-0685-8291-0593

> Valid until 14 December 2030

#### Energy rating and EPC

This property's current energy rating is C.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/4389-3917-9540-7550-2469).

#### Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

## Changes that pay for themselves within 3 years

Recommendation	Potential impact
Add time control to HWS secondary circulation.	High
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Changes that pay for themselves within 3 to 7 years	
Recommendation	Potential impact
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium

Some glazing is poorly insulated. Replace/improve glazing and/or frames.

Medium

Recommendation	Potential impact
Consider installing an air source heat pump.	Medium
Changes that pay for themselves in more than 7 years	
Recommendation	Potential impact
Roof is poorly insulated. Install or improve insulation of roof.	Medium
Property and report details	
Report issued on	
15 December 2020	

# Total useful floor area

441 square metres

# **Building environment**

Heating and Natural Ventilation

#### **Calculation tool**

DesignBuilder Software Ltd, DesignBuilder SBEM, v6.1.7, SBEM, v5.6.b.0

#### Assessor's details

Assessor's name Doug Whiffen

# Telephone

02476 233144

# Email

doug.whiffen@wensleylawz.com

# Employer's name

Wensley & Lawz Ltd

# **Employer's address**

116 Walsgrave Road Coventry CV2 4ED

# Assessor ID

# **Accreditation scheme**

Elmhurst Energy Systems Ltd

# Assessor's declaration

The assessor is not related to the owner of the property.

#### Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <u>mhclg.digital-</u> <u>services@communities.gov.uk</u>, or call our helpdesk on 020 3829 0748.

There are no related reports for this property.