Energy performance certificate (EPC)



Property type

A3/A4/A5 Restaurant and Cafes/Drinking Establishments and Hot Food takeaways

Total floor area

451 square metres

Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.


If a property has an energy rating of F or G, the landlord cannot grant a tenancy to new or existing tenants, unless an exemption has been registered.

From 1 April 2023, landlords will not be allowed to continue letting a non-domestic property on an existing lease if that property has an energy rating of F or G.

You can read <u>guidance for landlords on the regulations and exemptions</u> (<u>https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment_data/file/824018/Non-</u> Dom Private Rented Property Minimum Standard - Landlord Guidance.pdf).

Energy efficiency rating for this property

This property's current energy rating is C.



Properties are given a rating from A+ (most efficient) to G (least efficient).

Properties are also given a score. The larger the number, the more carbon dioxide (CO2) your property is likely to emit.

How this property compares to others

Properties similar to this one could have ratings:

If newly built

If typical of the existing stock

Breakdown of this property's energy performance

Main heating fuel Natural Gas

Building environment

Heating and Natural Ventilation



29 | B

Assessment level

3

Building emission rate (kgCO2/m2 per year)

95.49

Primary energy use (kWh/m2 per year)

551.53

What is primary energy use?

Recommendation report

Guidance on improving the energy performance of this property can be found in the <u>recommendation report (/energy-certificate/6688-8482-2204-3347-0559)</u>.

Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

Assessor contact details

Assessor's name

Richard Siddall

Telephone

02476 233144

Email

richard.siddall@wensleylawz.com

Accreditation scheme contact details

Accreditation scheme

Elmhurst Energy Systems Ltd

Assessor ID

EES/007509 https://find-energy-certificate.digital.communities.gov.uk/energy-certificate/8037-4255-3129-9142-4357

Telephone

01455 883 250

Email

enquiries@elmhurstenergy.co.uk

Assessment details

Date of assessment 1 August 2020

Date of certificate

22 November 2020

Employer

Wensley & Lawz Ltd

Employer address

116 Walsgrave Road Coventry CV2 4ED

Assessor's declaration

The assessor is not related to the owner of the property.

Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <u>mhclg.digital-</u> <u>services@communities.gov.uk</u>, or call our helpdesk on 020 3829 0748.

There are no related certificates for this property.

Energy performance certificate (EPC) recommendation report

THE RISING SUN PUBLIC HOUSE 46 EBURY BRIDGE ROAD LONDON SW1W 8PZ

Certificate number 6688-8482-2204-3347-0559

> Valid until 21 November 2030

Energy rating and EPC

This property's current energy rating is C.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/8037-4255-3129-9142-4357).

Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

Changes that pay for themselves within 3 years

Recommendation	Potential impact
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Changes that pay for themselves within 3 to 7 years	
Recommendation	Potential impact
Some windows have high U-values - consider installing secondary glazing.	Medium
Changes that pay for themselves in more than 7 years	
Recommendation	Potential impact

Triz4/2020 Energy performance of buildings register	21
Recommendation	Potential impact
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC ca	alculation. Medium
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing PV.	Low
Additional recommendations	
Recommendation	Potential impact
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Consider replacing non-LED lighting with LED equivalents	Medium
Property and report details	
Report issued on	
22 November 2020	
Total useful floor area	
451 square metres	
Building environment Heating and Natural Ventilation	
Calculation tool DesignBuilder Software Ltd, DesignBuilder SBEM, v6.1.7, SI	BEM, v5.6.b.0
Assessor's details	
Assessor's name	
Richard Siddall	

Telephone

02476 233144

Email

richard.siddall@wensleylawz.com

Employer's name

Wensley & Lawz Ltd

Employer's address

116 Walsgrave Road Coventry CV2 4ED

Assessor ID

EES/007509

Accreditation scheme

Elmhurst Energy Systems Ltd

Assessor's declaration

The assessor is not related to the owner of the property.

Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <u>mhclg.digital-</u> <u>services@communities.gov.uk</u>, or call our helpdesk on 020 3829 0748.

There are no related reports for this property.