# Energy performance certificate (EPC)



## Property type

A3/A4/A5 Restaurant and Cafes/Drinking Establishments and Hot Food takeaways

#### **Total floor area**

456 square metres

#### Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.


If a property has an energy rating of F or G, the landlord cannot grant a tenancy to new or existing tenants, unless an exemption has been registered.

From 1 April 2023, landlords will not be allowed to continue letting a non-domestic property on an existing lease if that property has an energy rating of F or G.

You can read guidance for landlords on the regulations and exemptions (https://assets.publishing.service.gov.uk/government/uploads/system/uploads/attachment data/file/824018/Non-Dom Private Rented Property Minimum Standard - Landlord Guidance.pdf).

#### **Energy efficiency rating for this property**

This property's current energy rating is C.



Properties are given a rating from A+ (most efficient) to G (least efficient).

Properties are also given a score. The larger the number, the more carbon dioxide (CO2) your property is likely to emit.

### How this property compares to others

Properties similar to this one could have ratings:

## If newly built

29 | B

# If typical of the existing stock

84 | D

## Breakdown of this property's energy performance

► What is primary energy use?

## **Recommendation report**

Guidance on improving the energy performance of this property can be found in the <u>recommendation report</u>.

#### Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

## Assessor contact details

#### Assessor's name

Doug Whiffen

## **Telephone**

02476 233144

## Accreditation scheme contact details

#### Accreditation scheme

Elmhurst Energy Systems Ltd

## **Assessor ID**

EES/007512

## **Telephone**

01455 883 250

# **Assessment details**

#### Date of assessment

17 September 2020

#### Date of certificate

29 September 2020

## **Employer**

Wensley & Lawz Ltd

## **Employer address**

116 Walsgrave Road Coventry CV2 4ED

### Assessor's declaration

## The assessor is not related to the owner of the property.

## Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a>, or call our helpdesk on 020 3829 0748.

There are no related certificates for this property.

# Energy performance certificate (EPC) recommendation report

PLOUGH INN HIGH STREET WRINGTON BS40 5QA Certificate number 9293-8963-6512-0680-4335

Valid until **28 September 2030** 

#### **Energy rating and EPC**

This property's current energy rating is C.

For more information on the property's energy performance, <u>see the EPC for this property (/energy-certificate/8451-2680-2279-7348-1314)</u>.

#### Recommendations

Make these changes to improve the property's energy efficiency.

Recommended improvements are grouped by the estimated time it would take for the change to pay for itself. The assessor may also make additional recommendations.

Each recommendation is marked as low, medium or high. This shows the potential impact of the change on reducing the property's carbon emissions.

## Changes that pay for themselves within 3 years

Recommendation	Potential impact
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
Changes that pay for themselves within 3 to 7 years	
Recommendation	Potential impact
Some windows have high U-values - consider installing secondary glazing.	Medium
Some solid walls are poorly insulated - introduce or improve internal wall insulation.	Medium
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium

Changes that pay for themselves in more than 7 years

Recommendation	Potential impact
Roof is poorly insulated. Install or improve insulation of roof.	Medium
Consider installing solar water heating.	Low
Consider installing PV.	Low

### Property and report details

## Report issued on

29 September 2020

## Total useful floor area

456 square metres

## **Building environment**

Heating and Natural Ventilation

## **Calculation tool**

DesignBuilder Software Ltd, DesignBuilder SBEM, v6.1.7, SBEM, v5.6.b.0

#### Assessor's details

#### Assessor's name

Doug Whiffen

## **Telephone**

02476 233144

## Employer's name

Wensley & Lawz Ltd

## Employer's address

116 Walsgrave Road Coventry CV2 4ED

#### **Assessor ID**

EES/007512

## **Accreditation scheme**

Elmhurst Energy Systems Ltd

# Assessor's declaration

The assessor has not indicated whether they have a relation to this property.

## Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a>, or call our helpdesk on 020 3829 0748.

There are no related reports for this property.